# **MERTIK MAXITROL®**

## **G60-ZMA3 Mains Adapter**

#### **OPERATING INSTRUCTIONS**

### FOR OEM USE ONLY

#### **WARNING**

Read these instructions carefully and completely before installing or operating.

Do NOT use a product if you suspect it has been subjected to high temperatures, damaged, tampered with, or taken apart.



Figure 1: G60-ZMA3 contents

#### **TECHNICAL DATA**

DIN EN60335-1 Approval:

100-240 V; 50/60 Hz; 0.2A Input:

6.0 V; 1000 mA Output:

Cable Length: 3 m

#### **INSTRUCTIONS**

1. Choose the appropriate outlet plug (see figure 2). Australian outlet plug available upon request.



Figure 2





2. Place the longer tabs on the plug end into the corresponding tab cutouts of the adapter (see figure 3).




Figure 3

3. Push down and then slide forward until the plug snaps into place (see figure 4).



Figure 4

4. To remove the plug, press down on the release button while sliding out the plug (see figure 5). Lift the plug out at the tab cutouts.




Figure 5

### **MERTIK MAXITROL**

www.mertikmaxitrol.com © 2016 Mertik Maxitrol GmbH & Co. KG All Rights Reserved.