



Selectra Series 14 Circuit Analysis

Part 5: Sensitivity Dial Testing

Swipe for step-by-step instructions →





Sensitivity Dial Testing

1. Dial pointer should align with mark on face label.
2. If rapid oscillation of the burner is occurring, rotate the dial counterclockwise in small increments allowing time for flame stabilization to occur. Do NOT rotate dial further than is required for stabilization.